

HIMACHAL PRADESH  
PUBLIC WORKS DEPARTMENT

\*\*\*\*\*

No. PWD/KB/CB/WA/building safety/2021-22

6668-6669

Dated: 20-12-2021

To

The Principal,  
Lotus International Convent School,  
Rakkar at Sadwan District Kangra.

Subject:-

Building safety certificate of Lotus International Convent  
School Rakkar at Sadwan District Kangra.

Reference: -

Your letter No:- LICS/BSC/599/2021 Dated:-6/12/2021.

Enclosed please find herewith building Safety Certificate  
of Lotus International Convent School Rakkar at Sadwan District Kangra HP for  
favour of information and further necessary action please

DA/ As above

Executive Engineer,  
Kotla Behar Division,  
HPPWD, Kotla Behar.

Copy to the Assistant Engineer, HP, PWD, Sub Division,  
Pragpur for information w.r.t. his office letter No 2170 dated 29/12/2021.

Executive Engineer,  
Kotla Behar Division,  
HPPWD, Kotla Behar


### Building Safety Certificate


The School building of "Lotus International Convent School ", Situated at Rakkar at Sadwan Tehsil- Rakkar, District- Kangra, H.P. inspected by me with Junior Engineer Pragpur Section. The buildings has neither been designed nor constructed by this department. No earthquake resistant norms have been adopted for this building. No structure drawings approved by the competent Government agency have been produced. The structure is a non-engineering structure. Hence, the structural safety of this building cannot be ensured especially from earthquake point of view. This department will not be responsible for any type of loss of life etc. if the structure fails under any circumstances. Building was constructed during the year 2012.


However, at present the building appears to be safe by visual inspection for next five year use.

Place: - Rakkar

Dated:-

  
Junior Engineer,  
HPPWD Section,  
Pragpur

  
Assistant Engineer,  
HPPWD Sub Division,  
Pragpur.

9/s  
  
Executive Engineer  
Kotla Behar Division  
HPPWD Kotla Behar